

Hall, Chelo

From: Kenny Blake <kenny@cochitigolfclub.com>
Sent: Saturday, August 20, 2016 3:59 PM
To: Hall, Chelo
Cc: Kenny Blake
Subject: Well # 1 Blow Off Valve - Corrective Compliance Plan # 5
Attachments: Blow Off Valve - Corrective Compliance Plan # 5.jpg

Chelo - Please see the attached picture of the Well # 1 Blow Off Valve. This satisfies Corrective Compliance Plan # 5. We repaired the plumbing and tested our Water Tank filler as a Blow Off Valve. We are able to isolate the flow of water and use this system as our Blow Off Valve.

Thanks - kb

Kenny Blake PGA | Cochiti Community Development Corporation
Chief Executive Officer

5200 Cochiti Highway
Cochiti Lake, NM 87083
T (505) 465-2210 x 11 | **F** (505) 465-0160

kenny@cochitigolfclub.com
www.cochitigolfclub.com | *Professional. Precision. Performance.*

CONFIDENTIALITY NOTICE

This e-mail and any attachments are for the sole use of the intended recipients and contain information that may be confidential or legally privileged. If you have received this e-mail in error, please notify the sender by reply e-mail and delete the message. Any disclosure, copying, distribution, or use of this communication by someone other than the intended recipient is prohibited.